

## County Surveyor's Record, Douglas County, Oregon

44

Resurvey of a  
 Portion of the South Bdy. of T 29 S., R. 1 W.,  
 As surveyed by Ernest P. Rands, Deputy Surveyor,  
 Under contract No 790, dated Oct. 18, 1909.

## CHAINS

I begin at the cor. of secs. 3, 4, 33 and 34 on the South Bdy. of the Tp. which is a cedar 12 ins. diam., marked and witnessed as described by the Surveyor General.

Thence I run

North 89°53'E. retracing the S. Bdy. of sec. 34.

39.50 Intersect the  $\frac{1}{4}$  sec. cor. which is a stone, 6x5x5 ins. above ground, firmly set, marked and witnessed as described by the Surveyor General.

83.03 Intersect the cor. of secs. 2, 3, 34 and 35 which is a stone, 8x7x5 ins. above ground, firmly set, marked and witnessed as described by the Surveyor General.

Thence I run

East retracing the S. Bdy. of sec. 35.

39.95 Intersect the  $\frac{1}{4}$  sec. cor. on N. Bdy. of sec. 2, T 30 S., R. 1 W.

79.59 My line falls 23 lks. N. of the cor. of secs. 1 and 2.

Thence I run

East retracing the N. Bdy. of sec. 1.

40.49 Intersect the old  $\frac{1}{4}$  sec. cor.

81.18 My line falls 25 lks. S. of the old NE. cor. of T. 30 S., R. 1 W.

Thence from the old Tp. cor., I run

East retracing the S. Bdy. of sec. 36.

29.84 Intersect the cor. of Tps. 29 and 30 S., R. 1 W. which is a stone, 6x5x5 ins. above ground, firmly set, marked and witnessed as described by the Surveyor General.

July 24, 1910.

At the cor. of secs. 33 and 34 on the S. Bdy. of the Tp. heretofore described.

Thence I run

N. 89°53'E. resurveying the S. Bdy. of sec. 34.