

129

Subdivisions, T. 29 S., R. 1 W.

CHAINS

A fir, 18 ins. diam., bears N.55*E., 31 lks. dist.,
marked $\frac{1}{2}$ S 1 B T.

A fir, 20 ins. diam., bears N.89*W., 20 lks. dist.,
marked $\frac{1}{2}$ S 2 B T.

Desc. NE. slope, 487 ft.

49.30 Desc. N. slope.

58.33 Creek, 8 lks. wide, course NE., asc. SE. slope, 100 ft.

63.20 Top of spur, slopes E., desc. NE. slope, 172 ft.

75.92 Slick Creek, 18 lks. wide, course SE., thence along W.
slope.

80.20 Trail, bears NW. and SE.

80.44 Intersect S. bdy. of T. 28 S., R. 1 W., 7.66 chs. S.89*39'E.,
from the $\frac{1}{2}$ sec. cor. of sec. 35.

At the point of intersection,

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins in the
ground, for closing cor. of secs. 1 and 2, with brass
cap marked

T28SR1WS35	
S2	S1
T29S	R1W
C	C
1922	

from which

A hemlock, 8 ins. diam., bears S.41*E., 15 lks. dist.,
marked T 29 S R 1 W S 1 C C B T.

A fir, 10 ins. diam., bears S.41*W., 18 lks. dist.,
marked T 29 S R 1 W S 2 C C B T.

Land, mountainous.

Soil, rocky loam, 4th. rate.

Timber, fir, pine, hemlock, chinquapin and cedar.

Undergrowth, salal, vine maple, and rhododendron.

GENERAL DESCRIPTION

The land of this township is in general, rough and
mountainous, covered with heavy timber and dense under-
growth. South of Dumore Creek there are many benches