

East Boundary of T. 29 S., R. 3 W.

CHAINS

North on East Boundary of Section 12.

Var.18*E.

1.00 Creek 1 link wide, course S.E.

40.00 Set Yew post for $\frac{1}{4}$ Sec. Corner, from which
 Fir 30 ins. diam. bears S.20*E. 9 lks.
 Fir 24 ins. diam. bears West. 16 lks.

46.50 Creek 2 lks. wide, course S.E.

66.00 Enter Marshy flat.

70.00 Leave same.

80.00 Set Cedar post for corner to Secs. 1,6,7,12, from which
 Laurel 15 ins. diam. bears N.8*E. 45 lks.
 Fir 18 ins. diam. bears S.72*E. 24 lks.
 Fir 30 ins. diam. bears S.20*W. 18 lks.
 Fir 28 ins. diam. bears N.48*W. 50 lks.

Land mountainous, rocky 3rd rate.

Timber, generally good.

North, on East Boundary of Section 1.

Var.19*E.

22.00 Begin steep descent.

30.00 Enter broken rocky slide.

40.00 Set Hemlock post for $\frac{1}{4}$ Sec. corner, from which
 A Fir 15 ins. diam. bears N.30*W. 21 lks.
 Hemlock 20 ins. diam. bears S.40*E. 30 lks.

70.00 Leave rocky slide.

80.00 Set Temporary corner.

78.95 Established permanent corner for Townships 28 & 29 S.,
 Ranges 2 & 3 West.

Land, mountainous, rocky, broken, 3rd rate.

Timber, small, chiefly fir.

At this date I test my instruments, as per instructions.

April 16.