

Resurvey and Survey North Bdy., T. 29 S., R 2 W.

CHAINS

set, marked and witnessed as described by the surveyor general. I perpetuate this cor., as follows; alongside the old cor.

Set a granite stone, 14x14x6 ins., 9 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 32, T. 28 S., R. 2 W. only, marked $\frac{1}{4}$ on N. face; from which

A hemlock, 36 ins. diam., bears N.11*E., 68 lks. dist., marked $\frac{1}{4}$ S 32 B T (New B.T.)

A hemlock, 36 ins. diam., bears N.13*W., 28 lks., dist. marked $\frac{1}{4}$ S 32 B T (Old B.T.)

Thence

N.89*50'E., continuing my measurements.

80.00 Set a granite stone, 14x10x7 ins., 9 ins. in the ground, for cor. of secs. 4 and 5, marked with 2 notches on W. and 4 notches on E. edge; from which

A hemlock, 9 ins. diam., bears S.30*30'E., 41 lks. dist., marked T 29 S R 2 W S 4 B T.

A hemlock, 6 ins. diam., bears S.48*30'W., 40 lks. dist., marked T 29 S R 2 W S 5 B T.

Land, mountainous..

Soil, gravelly, 3rd rate.

Timber, fir, hemlock and cedar.

Undergrowth, maple, rhododendron and young timber.

N.89*50'E., resurveying N.bdy. of sec. 4.

Descend NE. slope, through heavy timber and dense undergrowth.

0.50 Creek, 3 lks. wide, course N.; ascend.

11.00 Top of spur, slopes NW.; descend.

21.20 Creek, 2 lks. wide, course N.; ascend.

36.12 Intersect the cor. of secs. 32 and 33, T. 28 S., R. 2 W., which is a granite stone, firmly set, marked and witnessed as described by the surveyor general.

Thence

N.89*27'E., continuing my measurements

38.60 Top of spur, slopes NW.; along N. slope.