

6246  
30

County Surveyor's Record, Douglas County, Oregon

Subdivision of T.29S., R. 2 W.

CHAINS

marked  $\frac{1}{4}$  S 25 B T.

Cor. No. 6 on Homestead Entry Survey No. 140, which is a stone, firmly set, marked and witnessed as described by the surveyor general, bears S.74\*55'E., 18.72 chs. dist.,

47.10 Creek, 1 lk. wide, course NW.

54.30 Draw, course NW.; along N. slope.

69.00 Descend NW. slope.

81.22 The cor. of secs. 23, 24, 25 and 26.

Land, mountaknous.

Soil, rocky, 3rd rate.

Timber, fir, pine and cedar.

Undergrowth, maple, willow and wild lilac.

---

N.0\*08'E., on a Sectional Guide Meridian, bet. secs. 23 and 24.

Along W. slope, through heavy timber and dense undergrowth.

1.17 Deadman Creek, 25 lks. wide, course SW.; ascend.

12.10 Top of spur, slopes E.; descend.

26.50 Same creek, course SE.; ascend.

35.35 Top of ascend; along W. slope.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked.

$\frac{1}{4}$   
S23 | S24  
1917

from which

A fir, 20 ins. diam., bears S.88\*E., 8 lks. dist., marked  $\frac{1}{4}$  S 24 B T.

A fir, 36 ins. diam., bears N.49\*45'W., 39 lks. dist., marked  $\frac{1}{4}$  S 23 B T.

58.45 Deadman Creek, 20 lks. wide, course SW.; ascend.

76.50 Creek, 2 lks. wide, course SE.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 13, 14, 23 and 24, with brass cap marked

T29S R2W  
S14 | S13  
S23 | S24  
1917