

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 2 W.

CHAINS	<p>Land, mountainous.</p> <p>Soil, gravelly, 3rd rate.</p> <p>Timber, fir, pine and cedar.</p> <p>Undergrowth, maple, rhododendron, chinquapin and young timber.</p>
15.40	<p>N.0°08'E., on a Section Guide Meridian, bet. secs. 11 and 12.</p> <p>Along E. slope, through heavy timber and dense undergrowth.</p>
40.00	<p>Creek, 8 lks. wide, course SE.; ascend.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked</p> <div style="text-align: center; margin: 10px 0;"> $\begin{array}{c} \frac{1}{4} \\ S11 S12 \\ 1917 \end{array}$ </div> <p>from which</p> <p style="padding-left: 40px;">A cedar, 32 ins. diam., bears N.45°30'E., 25 lks. dist., marked $\frac{1}{4}$ S 12 B T.</p> <p style="padding-left: 40px;">A pine, 12 ins. diam., bears N.60°15'W., 63 lks. dist., marked $\frac{1}{4}$ S 11 B T.</p>
43.20	<p>Top of spur, slopes SE.; along E. slope.</p>
60.00	<p>Ascend SW. slope.</p>
69.20	<p>Trail, bears NW. and SE.</p>
80.00	<p>Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 1, 2, 11 and 12, with brass cap marked</p> <div style="text-align: center; margin: 10px 0;"> $\begin{array}{c} T29S R2W \\ S2 S1 \\ \hline S11 S12 \\ 1917 \end{array}$ </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 30 ins. diam., bears N.80°E., 46 lks. dist., marked T 29 S R 2 W S 1 B T.</p> <p style="padding-left: 40px;">A pine, 36 ins. diam., bears S.45°E., 122 lks. dist., marked T 29 S R 2 W S 12 B T.</p> <p style="padding-left: 40px;">A pine, 40 ins. diam., bears S.23°W., 90 lks. dist., marked T 29 S R 2 W S 11 B T.</p> <p style="padding-left: 40px;">A pine, 24 ins. diam., bears N.49°W., 63 lks. dist., marked T 29 S R 2 W S 2 B T.</p>