

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 29 S., R. 2 W.

CHAINS	<p>N.89*49'E., on a true line, bet. secs. 6 and 7.</p> <p>Ascend through heavy timber and dense undergrowth.</p> <p>14.40 Top of spur, slopes NW., along N. slope.</p> <p>33.40 Top of spur, slopes N.</p> <p>44.43 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked</p> <div style="text-align: center;"> $\frac{1}{4} \frac{S6}{S7}$ <p>1917</p> </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears N.34*W., 29 lks. dist., marked $\frac{1}{4}$ S 6 B T.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S.27*W., 22 lks. dist., marked $\frac{1}{4}$ S 7 B T.</p> <p>52.40 Stream, 1 lk. wide, course N., ascend.</p> <p>65.40 Top of ridge, bears S.W. and E.; along top of ridge.</p> <p>82.90 Leave top of ridge, bears NE. and W.</p> <p>84.43 The cor. of secs. 5, 6, 7 and 8.</p> <p>Land, mountainous.</p> <p>Soil, light gravelly and rocky loam, 3rd rate.</p> <p>Timber, fir, cedar and hemlock.</p> <p>Undergrowth, maple and rhododendron.</p> <hr/> <p>N.0*20'E., on a random line, bet. secs. 5 and 6.</p> <p>37.03 Intersect the N. bdy. of the Tp., 3 lks. E. of the cor. of secs. 5 and 6.</p> <p>Thence</p> <p>S.0*17'W., on a true line, bet. secs. 5 and 6.</p> <p>Descend through heavy timber and dense undergrowth.</p> <p>2.40 Creek, 2 lks. wide, course W.; ascend.</p> <p>19.30 Creek, 1 lk. wide, course NW.</p> <p>35.50 Top of ridge, bears E. and W.; descend.</p> <p>37.03 The cor. of secs. 5, 6, 7 and 8.</p> <p>Land, mountainous.</p> <p>Soil, light gravelly and rocky loam, 3rd rate.</p> <p>Timber, fir, cedar and hemlock.</p> <p>Undergrowth, maple, rhododendron and young timber.</p>
--------	--