

County Surveyor's Record, Douglas County, Oregon

Subdivisions of Fractional T. 29 S., R. 3 W.

CHAINS		
	Balance timbered with Fir, Pine, Oak and Cedar. Soil, 2nd rate.	
	East, bet. Secs. 28 and 33.  Var. 16*45'E.	
23.50	Branch, 8 lks. wide, C. S.	-200
40.00	A Cedar, 6 ins. diam., $\frac{1}{4}$ sec. post, from which A Fir, 15 ins. diam., bears S.70*E., 12 lks. dist. A Fir, 12 ins. diam., bears N.75*W., 10 lks. dist.	+20
54.85	Creek, 20 lks. wide, C. S.	-20
57.00	Enter prairie, C. N. and SE.	lev.
62.00	Leave same, C. NW and SW.	"
73.80	Branch, 10 lks. wide, C. W. and NW.	"
80.00	Set post cor. Secs. 27, 28, 33 and 34, from which A Fir, 10 ins. diam., bears S.89*W., 53 lks. dist. A Fir, 10 ins. diam., bears N.89*W., 51 lks. dist. A Fir, 15 ins. diam., bears N.62*E., 73 lks. dist. A Fir, 24 ins. diam., bears S.70*E., 76 lks. dist.  First half, rolling, balance level. Timber, Fir, Cedar, Maple, Pine and Laurel. Undergrowth, Hazel, Oak, Salal, and Grape. Soil, 2nd rate.	"
	South, between Secs. 33 and 34.  Var. 16*30'E.	
3.10	Branch, 10 lks. wide, C. W.	lev.
10.60	Marked a Fir, 36 ins. diam., from which A Fir, 24 ins. diam., bears N.85*W., 18 lks. dist. A Fir, 6 ins. diam., bears N.25*E., 37 lks. dist.  Land South of this corner too mountainous for settlement or cultivation.	+50