

County Surveyor's Record, Douglas County, Oregon

Exteriors of T. 29 S., R. 3 W.

CHAINS	<p>Timber, poor, chiefly Fir and Cedar.</p> <p style="text-align: right;">April 15, 1881.</p>
	<p>North, on East Boundary of Section 24.</p> <p style="text-align: right;">Var. 18°E.</p>
40.00	<p>Set Fir post for <math>\frac{1}{4}</math> Sec. cor., from which</p> <p style="padding-left: 40px;">A Fir, 36 ins. diam., bears N.75°E., 23 lks.</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears N.70°W., 26 lks.</p>
50.00	<p>Top of ridge, C. SW.</p>
80.00	<p>Set Maple post for cor. to Secs. 13, 18, 19 and 24,</p> <p style="padding-left: 40px;">from which</p> <p style="padding-left: 80px;">A Fir, 24 ins. diam., bears N.55°E., 7 lks.</p> <p style="padding-left: 80px;">A Fir, 18 ins. diam., bears S.53°E., 24 lks.</p> <p style="padding-left: 80px;">A Fir, 24 ins. diam., bears S.65°W., 58 lks.</p> <p style="padding-left: 80px;">A Fir, 30 ins. diam., bears N.80°W., 26 lks.</p> <p>Land, mountainous, 2nd rate.</p> <p>Timber, good - chiefly Fir and Cedar.</p>
	<p>North on East Boundary of Section 13.</p> <p style="text-align: right;">Var. 17°30'E.</p>
40.00	<p>Set Fir post for <math>\frac{1}{4}</math> sec. cor., from which</p> <p style="padding-left: 40px;">A Laurel, 8 ins. diam., bears N.75°E., 14 lks.</p> <p style="padding-left: 40px;">A Laurel, 5 ins. diam., bears S.38°W., 29 lks.</p>
48.20	<p>Creek, 1 lk. wide, C. NW.</p>
74.40	<p>Creek, 25 lks. wide, C. SW.</p>
80.00	<p>Set Yew post for cor. to Secs. 7, 12, 13, 18, from</p> <p style="padding-left: 40px;">which</p> <p style="padding-left: 80px;">A Laurel, 12 ins. diam., bears N.35°E., 10 lks.</p> <p style="padding-left: 80px;">A Fir, 10 ins. diam., bears S.50°E., 19 lks.</p> <p style="padding-left: 80px;">A Fir, 10 ins. diam., bears S.12°W., 20 lks.</p> <p style="padding-left: 80px;">A Fir, 10 ins. diam., bears N.50°W., 17 lks.</p> <p>Land, mountainous, 2nd rate.</p> <p>Timber, good - chiefly Fir, Cedar and Pine.</p>