

County Surveyor's Record, Douglas County, Oregon

Exteriors of T. 29 S., R. 3 W.

CHAINS

A Fir, 12 ins. diam., bears N.23*W., 31 lks.
 Land, sloping West, brushy, 3rd rate.
 Timber, poor - chiefly Fir, Cedar and Hemlock.

West, on North Boundary of Section 2.

Va. 18*30'E.

0.90 Creek, 40 lks. wide, C. SW.
 4.90 Same, C. N.75*W.
 5.80 Enter same Creek and at
 9.25 Leave same, C. N.88*W.
 20.60 Same stream, C. SW.
 22.00 Trail, C. SW.
 40.00 Set Laurel post for $\frac{1}{4}$ sec. cor., from which
 A Fir, 40 ins. diam., bears S. 8 lks.
 A Laurel, 8 ins. diam., bears N.10*E., 36 lks.
 61.90 Creek, 3 lks. wide, C. SW.
 80.00 Set Laurel post for cor. to Secs. 2, 3, 34 and 35, from
 which
 A Cedar, 48 ins. diam., bears N.50*E., 70 lks.
 A Laurel, 20 ins. diam., bears S.15*E., 38 lks.
 A Cedar, 15 ins. diam., bears S.60*W., 35 lks.
 A Fir, 20 ins. diam., bears N.62*W., 60 lks.
 Land, narrow valley along creek, 1st rate.
 Timber, good Fir, Cedar, Pine and Hemlock.
 April 18, 1881.

West, on North Boundary of Section 3.

Va. 18*30'E.

8.50 Creek, 4 lks. wide, C. S.
 40.00 Set Laurel post for $\frac{1}{4}$ sec. cor., from which
 A Laurel, 12 ins. diam., bears S.32*W., 19 lks.
 A Laurel, 10 ins. diam., bears N.20*W., 33 lks.
 46.50 Top of ridge, C. SW.