

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 3 W.

CHAINS

Timber, chiefly Fir and Cedar.

April 20, 1881.

North, between Sections 23 and 24.

Va. $17\frac{1}{2}$ *E.

39.65 Creek, 5 lks. wide, C. NW.

40.00 Set a Hemlock post for the $\frac{1}{4}$ sec. cor., from which
 A Cedar, 18 ins. diam., bears S.26*E., 15 lks. dist.
 A Hemlock, 10 ins. diam., bears N.80*W., 18 lks.
 dist.

66.15 Stream, 30 lks. wide, C. S.15*W.,

79.25 Stream, 2 lks. wide, C. E.

80.00 Set Hemlock post for the cor. to Secs. 13, 14, 23 and
 24, from which

A Fir, 50 ins. diam., bears N.89*E., 23 lks. dist.

A Fir, 60 ins. diam., bears S.58*E., 38 lks. dist.

A Fir, 10 ins. diam., bears S.70*W., 40 lks. dist.

A Fir, 16 ins. diam., bears N.42*W., 44 lks. dist.

Land, mountainous, 2nd rate.

Timber, good, Fir, Cedar, Hemlock and Pine.

East, on Random line between Sections 13 and 24.

Va. 18*E.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.90 Intersect line 80 lks. North of cor. to Secs. 13, 18,
 19, 24.

N.89*26*W., on True line between Secs. 13 and 24.

12.50 Creek, 1 lk. wide, C. N.

28.50 Creek, 2 lks. wide, C. N.

39.95 Set a Fir post for the $\frac{1}{4}$ sec. cor., from which
 A Fir, 8 ins. diam., bears S.50*W., 15 lks. dist.