

County Surveyor's Record, Douglas County, Oregon

40

Subdivisions of T. 29 S., R. 3 W.

CHAINS		Va. 17*30'E.
0.50	Creek, 50 lks. wide, C. SW.	
40.00	Set Laurel post for the $\frac{1}{4}$ sec. cor., from which A Laurel, 10 ins. diam., bears N.62*E., 16 lks. dist. A Fir, 24 ins. diam., bears N.30*W., 10 lks. dist.	
79.40	Creek, 5 lks. wide, C. SW.	
80.00	Set Hemlock post for the cor. to Secs. 14, 15, 22 and 23, from which A Maple, 8 ins. diam., bears N.42*E., 20 lks. dist. A Fir, 18 ins. diam., bears S.65*E., 39 lks. dist. A Cedar, 48 ins. diam., bears S.60*W., 48 lks. dist. A Cedar, 44 ins. diam., bears N.65*W., 45 lks. dist. Land, mountainous, heavily timbered, 2nd rate. Timber good, chiefly Fir, Cedar, Pine, Hemlock, Alder and Maple. April 23, 1881.	
	East, on Random line between Sections 14 and 23. Va. 16*45'E.	
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
79.45	Intersect 98 lks. N. of cor. to Secs. 13, 14, 23 & 24. N.89*18'W., on True line between Secs. 14 and 23.	
1.45	Creek, 2 lks. wide, C. SE.	
27.00	Top of spur, C. SW.	
39.72	Set Maple post for $\frac{1}{4}$ sec. cor., from which A Laurel, 20 ins. diam., bears S.60*E., 44 lks. dist. A Fir, 24 ins. diam., bears N.78*W., 43 lks. dist.	
79.45	To Section corner. Land, mountainous, 2nd rate. Timber, good, chiefly Fir, Cedar, Pine, Hemlock and Laurel.	
	North, between Sections 14 and 15. Va. 16*45'E.	
34.00	Top of ridge, C. SW.	