

County Surveyor's Record, Douglas County, Oregon

Exteriors of T. 29 S., R. 4 W.

CHAINS

Timber, fine Fir, Cedar, Pine, Oak, Laurel, Maple.
Undergrowth, mostly young Firs, Oaks and Laurels, Hazel.

West, on Random line along South boundary of Sec. 34.
Va. 18*5'E.

38.66 $\frac{1}{2}$ sec. cor. bears N.233 lks.

77.51 Intersect N. & S. line, 311 lks. S. of cor. to Secs.
34 and 33.

I find here a post in place, but not marked, evidently set by Deputy Byars in 1872; also a stump of a Bl. Oak in Sec. 33, which corresponds in size and direction with the one in this Section, described in the Field notes furnished me; I run a line North from here 40 chs. in search of the $\frac{1}{2}$ post, but am unable to find any trace of post, bearing trees or any evidence of a line starting from here; neither has the line coming North from $\frac{1}{2}$ post between Secs. 3 and 4 been closed upon here. I restore this corner by setting an Oak post $4\frac{1}{2}$ ft. long, 4 ins. sq., 24 ins. in the ground, marked:

T29S R4W on N.

S34 on E.

S33 on W. faces, and 3 notches

on E. and W. faces, from which

A Fir, 8 ins. in diam., bears N.30 $\frac{1}{2}$ *E., 37 lks.
dist., marked: T29S R4W S34 BT.

A Fir, 8 ins. in diam., bears N.63 $\frac{1}{2}$ *W., 11 lks.
dist., marked: T29S R4W S33 BT.

Thence

S.88*51'E., on True South boundary of Sec. 34.

Va. 22*E.

Ascend through heavy underbrush of Laurels, Fir and
Hazel.