

Exteriors of T. 29 S., R. 4 W.

CHAINS	<p>West, on a Random line along South boundary of Sec. 33.</p> <p style="text-align: right;">Va. 22*E.</p>	
39.00	Set temp. $\frac{1}{2}$ sec. cor. No trace of bearing trees.	
78.00	Set temp. post to cor. of Secs. 32 and 33.	
	No signs of post or bearing trees.	
	<p>West, on a Random line along South boundary of Sec. 32.</p> <p style="text-align: right;">Va. 21*E.</p>	
37.45	$\frac{1}{2}$ sec. corner bears South 120 lks.	
76.80	Intersect N. & S. line 69 lks. S. of cor. to Secs. 32 and 31. The post is gone; only the bearing tree in Sec. 31 is left, a fire having burnt this locality a few years ago. I restore this corner by setting a Fir post, $4\frac{1}{2}$ ft. long, 4 ins. sq., 24 ins. in the ground, marked: T29S R4W on N.,	
	S32 on E.,	
	S31 on W. faces, and 5 notches on E.,	
	and 1 notch on W. face, from which	
	A Laurel, 12 ins. diam., bears N.30*W., 37 lks.	
	dist., marked T29S R4W S31 BT.	
	This is the original bearing tree, the marks of which, being dim, I remark same.	
	A Laurel, 4 ins. diam., bears N.68*E., 20 lks.	
	dist., marked T29S R4W S32 BT.	
	Thence	
	S89*E., on True South boundary of Sec. 32.	
	Va.21*30'E.	
	Descend through heavy underbrush of Laurels, Oaks and	
	Firs.	
6.50	Foot of descent, begin ascending	-60
10.50	Top of ascent.	+20
	Va.22*40'E.	
18.50	Foot of descent, begin ascent.	-100
22.50	Top of ascent, begin descent of S. slope of spur.	+35