

## County Surveyor's Record, Douglas County, Oregon

Exteriors of T. 29 S., R. 4 W.

CHAINS		
51.90	A branch, C. SW., 3 lks. wide, ascend big Fir timber. Va.19*45'E., Begin ascent, through Fir timber with	-200
66.10	heavy undergrowth. Va.21*10'E.	
77.00	The cor. to Secs. 33 and 34. Va.22*E. Land, mountainous. Soil, gravelly, 3rd rate. Timber, Fir, Pine, Laurel and Oak. Undergrowth, small Laurels, Firs, Oak and Hazel.	
52.51	West, on a Random line on South boundary of Sec. 31. Va.21*30'E. The locality of the $\frac{1}{2}$ sec. corner has been burnt over, destroying all traces. Intersect Offset of Meridian line 12.61 chs. North of the cor. to Tps. 29 and 30 S., Rs. 4 and 5. W. Thence N.76*30'E., on True South boundary of Sec.31. Va.29*30'E. Ascend Fir timber along S. slope.	
5.50	Top of ascent, begin descent.	+30
7.50	Branch course SW., 3 lks. wide.	
12.88	Set a Cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., mkd.: $\frac{1}{4}$ S on N. face, from which A Fir, 48 ins. diam., bears N.32*W., 19 lks. dist., mkd.: $\frac{1}{4}$ S BT. A Maple, 8 ins. diam., bears N.36*E., 74 lks. dist. mkd.: $\frac{1}{4}$ S BT. Keep ascending through open Fir timbers.	
16.00	Leave Fir timber, enter a burn covered with heavy undergrowth, ascending.	
34.00	Top of spur, C. NW. and SE. Va.21*20'E.	+250
41.50	Foot of descent; begin ascent.	-100
45.00	Top of spur, course NW. and SE.	+50
54.00	The cor. to Secs. 31 and 32. Land, mountainous.	