

## Subdivisions of T. 29 S., R. 4 W.

## CHAINS

Set a closing corner for Sections 8 and 17, at point of intersection, to wit:

A Fir post, 3 ins. sq., 3 ft. long, 24 ins. in the ground, scribed:

CCS8 on NW. face,

CCS17 on SW. face,

T29S R4W on NE face, with 4 notches on on S. & E. edges, from which

A Fir, 10 ins. diam., bears S.33\*W., 32 lks., scribed:

CCS17 T29S R4W BT.

A Laurel, 6 ins. diam., bears N.42\*W., 95 lks., scribed:

CCS8 T29S R4W BT.

Old corner to Secs. 9 & 16 bears S.7\*7'W., 5.24 chs.

Thence

West, on True line between Secs. 8 and 17.

Var. 18\*45'E.

3.25 Main divide between the two Myrtle Creeks, C. SW., which is about 1,000 ft. above the Valley land.

Descend steep brushy mountain.

27.25 Head steep canyon, C.NW.

28.25 Steep low ridge, C.NW.

31.25 To  $\frac{1}{4}$  sec. cor. between Secs. 8 and 17.

Land, mountainous.

Soil, stony, 4th rate.

Timber, Fir and Laurel, principally Fir.

Underbrush, dense.

April 14, 1899.

Thence

Commencing at the  $\frac{1}{4}$  sec. cor. between Secs. 17 and 18.

I made a new post and witness trees, (the old post and