

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 4 W.

CHAINS

witness trees still visable but badly decayed)

To wit:

A Fir post, 3 ins. sq., 3 ft. long, 24 ins. in the ground, scribed:

$\frac{1}{2}$ S17 on E. face,

$\frac{1}{2}$ S18 on W. face, from which

A Fir, 8 ins. diam., bears S.65*W., 33 lks., scribed: $\frac{1}{2}$ S18 BT.

A Fir, 6 ins. diam., bears N.40*E., 7 lks., scribed $\frac{1}{2}$ S17 BT.

April 15, 1899.

Thence

I run South on Random line to an intersection of the cor. to Secs. 17, 18, 19 and 20.

Var. 18*45'E.

41.45 Intersect 3.08 chs. N.89*30'E. of established cor. Secs. 17, 18, 19 and 20.

Re-established said corner as per old witness trees all standing in the original postion and by setting a new post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for Secs. 19 and 20, mkd.:

T29S S19 on SW.,

R4W ~~S20~~ on SE. face, with 5 notches on E., and 3 notches on S. edges.

I destroyed all marks referring to Secs. 17 and 18.

I then set closing corner to Secs. 17 and 18, at the point of intersection, to wit:

A Fir post, 3 ins. sq., 3 ft. long, 24 ins. in the ground, scribed:

CCS17 on NE. face,

CCS18 on NW. face,

T29S R4W on SE. and SW. faces, from

which