

55 X

Re-Survey of West Boundary of T. 29 S., R. 6 W.

CHAINS

Enter opening on S slope of mountain.

53.40 Rail fence, bears E and W.

80.00 The cor. of Tps. 29 and 30 S., Rgs. 6 and 7 W.

Land, mountainous.

Soil, clay and stony, 2nd and 3rd rate.

Timber, Red Fir, Sugar and Yellow Pine, Cedar, Oak.

Undergrowth, Arrowwood, Hazel, Fir, Oak.

Mountainous or heavily timbered land or land covered
with dense undergrowth. 80.00 chs.

July 29, 1905.

Re-Survey of South Bdy. of T. 29 S., R. 6 W.

At the cor. of Tps. 29 and 30 S., Rgs. 6 and 7 W.

As the falling of the line bet. Secs. 31 and 32 is out
of limits with the reported length of the S bdy. of
Sec. 31, from the above described corner, I run
S.89°54'E., bet. Secs. 6 and 31.

Over mountainous land through scattering timber and
dense undergrowth.

Descend SE slope.

.01 Rail fence, bears N and S.

.15 Rail fence, bears NE and SW.

.50 Rail fence bears NW and SE. Enter field.

1.50 Creek, 1 lk. wide, course S.

Ascend SW slope.

4.50 Rail fence, bears N and S.

13.00 Rail fence, bears NE and SW. Leave field.

18.50 Leave scattering timber and dense undergrowth, bears
NE and SW.

Enter rocky opening on S slope of mountain.

29.50 Enter heavy timber and dense undergrowth, bears N and S.

39.08 The $\frac{1}{4}$ Sec. cor., which is a post greatly decayed,
witnessed as described by the Surveyor General,
bears N. 29 lks. dist.