

County Surveyor's Record, Douglas County, Oregon

Re-Establishment of Corners in T. 29 S. R. 6 W.

CHAINS

A Cedar, 40 ins. diam., bears N.20*W., 26 lks. dist., marked $\frac{1}{4}$ S 31 B T.

A Red Fir, 14 ins. diam., bears S. 20*E., 18 lks. dist., marked $\frac{1}{4}$ S 6 B T.

The $\frac{1}{4}$ sec. cor. bet. secs. 5 and 32, on the South bdy. of T 29 S R 6 W, being partially obliterated, I re-establish this corner in its original position, as follows:

Set a slate stone 14x10x6 ins. $9\frac{1}{2}$ ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face, from which:

A White Oak, 6 ins. diam., bears N.46*W., 13 lks. dist., marked $\frac{1}{4}$ S 32 B T.

A White Oak, 9 ins. diam., bears S.40*W., 42 lks. dist., marked $\frac{1}{4}$ S 5 B T.

December 4, 1905.

Re-Survey of Subdivision Lines of T. 29 S. R. 6 W. of the Willamette Meridian, as surveyed by Fred Mensch, U.S. Deputy Surveyor, under his contract No, 757, dated September 14, 1904.

The cor. of secs. 19, 20, 29 and 30, at which I am instructed to commence the survey of the lines necessary to complete the subdivision of secs. 29, 30, 31, 32 and 33, T 29 S R 6 W, is not found after diligent search. I commence, therefore, at the cor. of secs. 17, 18, 19 and 20, which is an oak stake, 20 ins. above ground, marked and witnessed, as described by the Surveyor general.

Thence I run

South on a random line bet. secs. 19 and 20.

40.00 The $\frac{1}{4}$ sec. cor. is not found after careful search.

Set temp. $\frac{1}{4}$ sec. cor.

80.00 Again I make careful search for the cor. of secs. 19, 20,