

Resurvey of the North Bdy. of T. 30 S., R. 7 W.

CHAINS

- 80.00 Set a stone, 24 x 16 x 10 ins., 20 ins. in ground, for the corner to secs. 5, 6, 31 and 32, marked with 5 notches on the East and 1 notch on the West angles of the same, and from which,
- A Fir, 5 ins. diam., bears N.48*E., 14 lks. dist.
Marked T 29 S R 7 W S 32 B T.
- A Live Oak, 6 ins. diam., bears S.70*E., 12 lks. dist.
Marked T 30 S R 7 W S 5 B T.
- A Fir, 14 ins. diam., bears S.45*W., 76 lks. dist.
Marked T 30 S R 7 W S 6 B T.
- A Fir, 46 ins. diam., bears N.44*W., 56 lks. dist.
Marked T 29 S R 7 W S 31 B T.

Land, broken and mountainous.

Soil, rocky, second and third rate.

Timber, densely covered with Fir, Cedar, Pine, Laurel and Oak.

Undergrowth, thick, Pine and Laurel, with Live Oak, Hazel, Maple and Arrow wood.

South, 89*59'W., on a true line, between secs. 6 and 31.
Va. 19*30'E.

- 15.00 Top of steep ascent.
Moderate descent.
- 26.50 A creek, 6 lks. wide, Course S.60*E.
- 35.00 Along North slope of mountain.
- 40.00 Set a Fir post, 4 feet long, 4 ins. square, 20 ins. in ground, for the $\frac{1}{2}$ sec. corner, marked $\frac{1}{2}$ S. on the North face, and from which,
- A Fir, 12 ins. diam., bears N.25*E., 29 lks. dist.
Marked $\frac{1}{2}$ S. B T.
- A Chinquapin, 12 ins. diam., bears S.15*E., 36 lks. dist.