

County Surveyor's Record, Douglas County, Oregon

Resurvey of the North Bdy. of T. 30 S., R. 7 W.

CHAINS

Marked $\frac{1}{2}$ g., B T.

56.06 A spring branch, 1 lk. wide, Course S.

Moderate Ascent.

81.63 To the corner of Townships 29 S., Ranges 7 and 8 W.

Land, mountainous and broken.

Soil, third rate.

Timber, densly covered with Fir, Cedar, Pine, Laurel,
and Oak.Undergrowth, thick, Fir, Cedar, Pine, Laurel and Oak,
with Live Oak, Hazel and Arrow wood.

September 23, 1882.

General Description

The greater portion of this Township is hilly, mountainous and broken, with an occasional narrow bottom of good, first class lands. The mountains and hills are covered with dense forests of Fir, Pine, Cedar, Laurel, and other valuable timber. There are two or three settlements on the unsurveyed portion near the NE. and SW. parts. The township should be subdivided.

William H. Byars,

U. S. Deputy Surveyor.

Retracement of portion of South Bdy. of T. 29 S., R. 7 W.
As surveyed by Roy T. Campbell, Deputy Surveyor,
Under Contract No. 789, dated August 21, 1909.

I begin at the corner of secs. 1, 2, 35 and 36, on the South boundary, which is a post, badly decayed, but marked and witnessed as described by the Surveyor General; in place of the post I set a diorite stone, 15 x 8 x 6 ins., 10 ins. in the ground, mkd. with 1 notch on E. and 5 notches on W. edge.