

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 29 S., R. 7 W.

## CHAINS

Undergrowth, Chinquapin and Willow.

July 3: At this corner I set off 23°0' North on the declination arc, and at 12h 4m l.m.t., observe the sun on the meridian; the resulting latitude is 43°2'.

North, on a true line, on sectional guide meridian, between secs. 23 and 24.

Along W. slope, over mountainous land, through heavy timber and scattering undergrowth, exceptionally difficult to survey.

- 1.91 A trail, bears E. and W.
- 17.58 A spring branch, 1 lk. wide, course W.
- 40.00 Set a Fir post, 4 ins. square, 3 ft. long, 24 ins. in the ground, for  $\frac{1}{2}$  sec. corner, marked  $\frac{1}{2}$  S 23 on W., and 24 on E. face, from which,  
 A Fir, 24 ins. diam., bears S.52°30'E., 49 lks. dist.  
 Marked  $\frac{1}{2}$  S 24 B T.  
 A Fir, 14 ins. diam., bears N.26°30'W., 26 lks. dist.  
 Marked  $\frac{1}{2}$  S 23 B T.
- 55.73 A spring branch, 2 lks. wide, course W. Thence ascend SW. slope.
- 77.00 Top of ridge, bears S.60°E., N.60°W., 300 ft. above spring branch. Thence descend 10 ft., to
- 81.71 Intersect E. and W. line at the corner of secs. 13, 14, 23 and 24, which is a post, 4 ins. square, 12 ins. above ground, badly decayed. The bearing trees are dead.  
 I re-establish the corner at the same point, as follows:  
 Set a Cedar post, 4 ins. square, 3 ft. long, 24 ins. in the ground, for corner of secs. 13, 14, 23 and 24, marked T 29 S S 13 on NE., R 7 W S 24 on SE., S 23 on SW. and S 14 on NW., with 3 notches on S. and 1 notch