

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 8 W., W.M.

CHAINS	<p>An Oak, 12 ins. diam., bears N.87*E., 123 lks. dist.</p> <p>An Oak, 20 ins. diam., bears N.68*W., 94 lks. dist.</p>	
80.00	<p>Set post, cor. secs. 10, 11, 14 and 15, from which</p> <p>An Oak, 15 ins. diam., bears N.30*W., 58 lks. dist.</p> <p>An Oak, 10 ins. diam., bears S.12*E., 76 lks. dist.</p> <p>An Oak, 8 ins. diam., bears S.35*W., 63 lks. dist.</p> <p>A Pine, 36 ins. diam., bears N.40*E., 81 lks. dist.</p> <p>Land, etc., as last noted.</p>	+150
	<p>East on random bet. secs. 11 and 14.</p> <p style="text-align: right;">Va. 19$\frac{1}{2}$*E.</p>	
40.00	Set temp. $\frac{1}{2}$ sec. post.	
80.40	<p>Intersect N and S line, 22 lks. S of cor.</p> <p>S.89*51'W., on true line bet. secs. 11 and 14.</p>	
25.50	Summit of ridge, course NE and SW.	+200
40.20	<p>Set $\frac{1}{4}$ sec. post, from which</p> <p>A E Oak, 12 ins. diam., bears N.18*E., 96 lks. dist.</p> <p>A Laurel, 15 ins. diam., bears S.30*E., 55 lks. dist.</p>	-100
59.40	Branch, 3 lks. wide, course S.	-50
80.40	<p>To cor.</p> <p>Openings consisting of pine and oak timber.</p> <p>Soil 3rd rate.</p>	+100
	<p>North bet. secs. 10 and 11.</p> <p style="text-align: right;">Va. 19$\frac{1}{2}$*E.</p>	
8.00	Summit of ridge, course E and W.	+80
10.00	Enter thick timber, course E and W.	-40
40.00	<p>Set $\frac{1}{2}$ sec. post, from which</p> <p>A Laurel, 6 ins. diam., bears N.10*E., 24 lks. dist.</p> <p>A Fir, 40 ins. diam., bears N.38*W., 51 lks. dist.</p>	-300
43.00	Branch, 10 lks. wide, course NE.	-75
80.00	<p>Set post, cor. secs. 2, 3, 10 and 11, from which</p> <p>Built stone mound, post could not be driven.</p> <p>A Laurel, 12 ins. diam., bears N.57*E., 34 lks. dist.</p>	+150