

Resurvey of the North Boundary of T. 30 S., R 8 W., W.M.

CHAINS	
	<p>notches on the E and one notch on the W angles of the same for the cor to secs. 5 and 6, and from which</p> <p style="padding-left: 40px;">A Hemlock, 14 ins. diam., bears N.21*E., 32 lks. dist., marked T 29 S R 8 W S 32 B T.</p> <p style="padding-left: 40px;">A Cedar, 14 ins. diam., bears S.15*E., 32 lks. dist., marked T 30 S R 8 W S 5 B T.</p> <p style="padding-left: 40px;">A Fir, 36 ins. diam., bears S.30*W., 38 lks. dist., marked T 30 S R 8 W S 6 B T.</p> <p>Lands mountainous and broken.</p> <p>Soil 3rd rate and covered with dense forests of fir, laurel, pine, hemlock and cedar.</p> <p>Thick undergrowth of fir, laurel, pine, hemlock, and cedar with hazel and maple.</p> <p style="text-align: right;">Oct. 28th 1882.</p>
	<p>S.89*22*W., on North boundary of sec. 6.</p> <p style="padding-left: 100px;">Va. 19*E.</p>
0.78	<p>Old cor for secs. 5, 6, 31 and 32, which is a post, 4 ins. sq., firmly set in the ground and marked T 29 S S 32 on NE face, T 30 S S 5 on SE face, S 6 on SW and S 31 on NW face and from which</p> <p style="padding-left: 40px;">A Hemlock, 15 ins. diam., bears N.33*E., 26 lks. dist., marked T 29 S R 8 W S 32 B T.</p> <p style="padding-left: 40px;">A Fir, 30 ins. diam., bears S.50*E., 3 lks. dist., marked T 30 S R 8 W S 5 B T.</p> <p style="padding-left: 40px;">A Fir, 15 ins. diam., bears S.87*W., 74 lks. dist., marked T 30 S R 8 W S 6 B T.</p> <p style="padding-left: 40px;">A Hemlock, 15 ins. diam., bears N.75*W., 38 lks. dist., marked T 29 S R 8 W S 31 B T.</p>
40.98	<p>Old <math>\frac{1}{4}</math> sec. cor.</p>
47.65	<p>A creek, 5 lks. wide, course N.</p>
66.10	<p>A creek, 5 lks. wide, course N.</p>
85.95	<p>The cor. to tps. 29 and 30 S., Rgs. 8 and 9 W., which is a post firmly set in the ground and marked</p>