

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S.; R. 9 W.

CHAINS		
	N.89° 52'W. on True Line between Sections 12 and 13.	
9.80	A Branch, 15 lks. wide, course NE.	-40
29.40	Same, course SE.	+5
39.70	Set $\frac{1}{4}$ Sec. Post, from which	+10
	A Fir, 12 ins. diam., bears N.40°E., 24 lks. dist.	
	A Fir, 24 ins. diam., bears S.38°W., 20 lks. dist.	
42.00	Enter Oak openings, course N. and SW.	+2
75.00	Leave openings and enter Fir Timber, course NE. and SE.	
79.40	To Corner.	
	Land, undulating. Timber, Fir, Oak, and Maple.	
	Undergrowth, Oak, Hazel, Maple, and Laurel. Soil, 2nd rate.	
	North between Sections 11 and 12	
	Var. 19°10'E.	
30.10	A Fir, 50 ins. diam.	+60
30.75	A Branch, 8 lks. wide. C. E.	-10
40.00	Set $\frac{1}{4}$ Sec. Post, from which	
	A Fir, 15 ins. diam. bears S.77°W., 36 lks.	
	A Fir, 9 ins. diam. bears N.78°E., 12 lks.	
67.55	A Branch, 5 lks. wide. C. E.	-100
69.80	A Creek, 12 lks. wide. C. SE.	-10
80.00	Set Post Corner, Secs. 1, 2, 11, and 12 from which	+50
	A Fir, 10 ins. diam. bears S. 4°E., 33 lks.	
	A Fir, 12 ins. diam. bears N.50°E., 28 lks.	
	A Fir, 6 ins. diam. bears N.30°W., 49 lks.	
	A Fir 18 ins. diam. bears S.78°W., 38 lks.	
	Land Hilly.	
	Timber, Fir, Cedar, etc. Soil 2nd rate.	
	July 31, 1855	
	S.89°45'E. on Random between Sections 1 and 12	
	Var. 19°10'E.	
40.00	Set Temp. $\frac{1}{4}$ Section Post.	
80.00	Intersect E. Bdy., 47 lks. N. of Corner. Thence.	
	N.89°25'W. On True Line between Sections 1 and 12	
21.00	Enter Prairie C. N.E. & S. W.	-80