

## County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 9 W.,  
As surveyed by W. S. Champman, Deputy Surveyor  
Under contract No. 234, dated June 24, 1875.

CHAINS

From the post at the cor. of secs. 10, 11, 14, and 15 in Township 29 S., R. 9 W., the B. T'S. of which, still standing, agree with the field notes furnished by the Surveyer General, as follows:

A Fir, 30 ins. diam. bears S.60\*W., 176 lks.

A Fir, 10 ins. diam. bears N.48\*W., 88 lks.

A Fir, 15 ins. diam. bears S.30\*E., 30 lks.

A Fir, 20 ins. diam. bears N.50\*E., 6 lks.

West on true line bet. secs. 10 and 15.

Va. 20\*30'E.

Ascend steep rocky mountain.

24.00 Summit of mountain, SSW.

35.50 Ridge, S.

40.00 Set post 4 ft. long, 4 ins. diam., one ft. in ground, for  $\frac{1}{2}$  sec. cor., from which

A Cedar, 8 ins. diam. bears S.82\*W., 33 lks.

A Hemlock, 20 ins. diam. bears N.20\*W., 39 lks.

40.20 Brook 2 lks. wide runs SW., run along mountain side facing S.

80.00 Set post 4 ft. long, 5 ins. diam., one ft. in ground, for cor. of secs. 9, 10, 15, and 16, from which

A Hemlock, 10 ins. diam. bears N.52\*W., 24 lks.

A Hemlock 18 ins. diam. bears N.40\*E., 22 lks.

A Cedar, 14 ins. diam. bears S.62\*E., 23 lks.

A Hemlock, 30 ins. diam. bears S.45\*W., 11 lks.

Land mountainous.

Soil 3rd rate and rocky.

Timber, fir (greatly injured by fire), Yew, hemlock, and cedar. September 20, 1875.

North on true line bet. secs. 9 and 10.

Va. 20\*15'E.

Ascend mountain.

20.00 Mountain slopes SW.

26.00 Ridge, NW.

31.50 Ravine almost dry, SW.

40.00 Set post 4 ft. long, 4 ins. diam., one ft. in ground.