

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 9 W.,

CHAINS	<p>Land mountainous.</p> <p>Soil third rate and rocky.</p> <p>Timber scattering, fir, hemlock, cedar, yew.</p> <hr/> <p>North on random line between secs. 3 and 4.</p> <p>40.00 Set temp. $\frac{1}{4}$ post.</p> <p>79.67 Intersect N. bdy., 31 lks. E. of cor.</p> <p>South $0^{\circ}13'E.$ on true line.</p> <p style="text-align: right;">$Va. 20^{\circ}15'E.$</p> <p>18.00 Ravine W.</p> <p>39.67 Set $\frac{1}{4}$ post 4 ft. long, 4 ins. diam., one ft. in ground, from which</p> <p style="padding-left: 40px;">A cedar, 15 ins. diam. bears $N.41^{\circ}E.$, 29 lks.</p> <p style="padding-left: 40px;">A hemlock, 8 ins. diam. bears $S.40^{\circ}W.$, 39 lks.</p> <p>46.00 Brook 1 link wide runs W.N.W.</p> <p>68.00 Summit of high ridge, N.W.</p> <p>74.50 Deep dry ravine, N.W.</p> <p>Ascend steep hill.</p> <p>79.67 To Cor.</p> <p>Land mountainous and broken.</p> <p>Soil third rate.</p> <p>Timber good, fir, hemlock, cedar and yew.</p> <hr/> <p style="text-align: center;">Retracement of Portion of S. Bdy. of T. 29 S., R. 9 W. As surveyed by William M. Porter, Deputy Surveyor, Under Special Instructions, dated June 5, 1907, Independent of, but in connection with his contract No. 768, dated March 8, 1907.</p> <hr/> <p>From the cor. of secs. 4, 5, 32, 33, on S. bdy. of Township, which is a Post firmly set, marked and witnessed as described by the Surveyor General, I run East on S. bdy. of sec. 33.*****</p> <p>80.18 Intersect at point for cor. of secs. 3, 4, 33 and 34. Post badly decayed and three witness trees destroyed.</p>
--------	---