Subdivisions, T. 30 S., R. 1 W.

CHAINS		
52.80	Leave same, C. SW.	
71.00	Enter openings, C. NE. and SW.	+ 300
80.00	Set post corner secs. 14, 15, 22 and 23, from which	+ 200
	An oak, 12 ins. diam., bears N.75*W., 135 lks.	
	An oak, 8 ins. diam., bears S.63*W., 85 lks.	
	An oak, 18 ins. diam., bears N.10*E., 121 lks.	
	An oak, 15 ins. diam., bears S.25*E., 168 lks.	
	Land, hilly.	
	Timber, fir, cedar, pine, sugar pine and oak.	
	Soil, third rate.	
	NOTE: Homestead Entry Survey #195 By Frederick W. Rase	
	SEE C.S. FILE 65/67-7 A-J FOR 1916 GLO HES #195 ORIG. SURVEY	
	Commencing at corner of secs. 14, 15, 22 and 23, T. 30 S., R. 1 W., Willamette Mer., which is a post (badly decayed) 3 ins. sq., 12 ins. above ground, marks not distinguishable; bearing trees as described by the Surveyor General remain standing.	
	I destroy old post and in its place	
	Set a granite stone 15x6x6 ins., 10 ins. in the ground, mkd. with 2 notches on east and 3 notches on south edges, for corner of secs. 14, 15, 22 and 23.	

	West, on random bet. secs. 15 and 22.	
	Va. 18*35'E.	
40.00	Set temp. ¼ sec. post.	
79.30	Intersect N. and S. Line 80 lks. S. of corner.	
	North, 89*26'W. on true line bet. secs. 15 and 22.	
39.65	Set ¼ sec. post, from which	+ 50
	An oak, 18 ins. diam., bears N.85*W., 92 lks.	
	A pine, 30 ins. diam., bears S.6*E., 54 lks.	
49.00	Summit of rocky hill.	+ 75