

Resurvey of East Bdy., T. 30 S., R. 2 W.

CHAINS	
	Thence, North on E. bdy. of sec. 1.
8.50	Ridge point descending E.
12.50	Ravine, C. E.
40.00	Set a basalt stone 12x10x8 ins., 8 ins. in the ground for $\frac{1}{4}$ sec. corner on E. bdy. sec. 1, marked $\frac{1}{4}$ on W. face, from which A white oak, 14 ins. diam., bears S.70*W., 6 lks. dist., marked $\frac{1}{4}$ S 1 B T. A white oak, 4 ins. diam., bears N.81*W., 57 lks. dist., marked $\frac{1}{4}$ S 1 B T.
41.23	I re-establish the old $\frac{1}{4}$ sec. corner in its original position as the $\frac{1}{4}$ sec. corner on W. bdy. sec. 6, T. 30 S., R 1 W., only, as follows: Set a basalt stone 18x10x6 ins., 12 ins. in the ground for $\frac{1}{4}$ sec. corner on W. bdy. sec. 6, marked $\frac{1}{4}$ on E. face, from which A yellow pine, 28 ins. diam., bears N.71*E., 88 lks. dist., marked $\frac{1}{4}$ S 6 B T. A white oak, 12 ins. diam., bears S.2 $\frac{1}{2}$ *E., 107 lks. dist., marked $\frac{1}{4}$ S 6 B T.
	Asc. S. slope.
52.75	Trail bears NW. and SE.
67.00	Summit of ascent. Along W. slope.
81.85	The corner of Tps. 29 and 30 S., Rs. 1 and 2 W. Land, mountainous. Soil, clay and stony; second and third rate. Timber, fir, cedar, pine, oak; undergrowth, vine maple, madrona, fir and hazel. Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey, 81.85 chs.