

Dependent Resurvey of Portion of South Boundary
of T. 30 S., R. 1 W.

CHAINS

Soil, rocky, fourth rate.
Timber, fir, pine, cedar, and yew.
Undergrowth, vine maple, yew, and hazel.

East, on S. bdy. of sec. 34.

Over mountainous land, through heavy timber and dense undergrowth.

Desc. 35 ft. over NE. slope.

0.40 Creek, 2 lks. wide, C. NW.

6.56 Creek, 6 lks. wide, C. N.

7.46 Ascend 355 ft. over NW. slope, through old burn.

18.84 Spur, slopes NE.; desc. 238 ft. to $\frac{1}{4}$ sec. cor., over NE. slope.

33.94 W. edge of small rocky prairie, bears N. and SE.

37.79 40.00 chs. westing from the closing cor. of secs. 2 and 3, determined as hereinafter described.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 3 only, with brass cap marked

$\frac{1}{4}$ S3
1923

from which

A fir, 30 ins. diam., bears S.84*W., 342 lks. dist., marked $\frac{1}{4}$ S 3 B T.

No other trees within limits; raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, S. of cor.

40.52 The old $\frac{1}{4}$ sec. cor., indicated by small mound of stone in which the post was originally set. The original bearing trees are dead and fallen.

I now change this cor. to refer to sec. 34 only.

In place of the decayed post

Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground, surrounded by a mound of stone, 3 ft. base, 1 $\frac{1}{2}$