

County Surveyor's Record, Douglas County, Oregon

Retracement and Dependent
Resurvey of Portion of Subdivisional Lines

in T. 30 S., R. 1 W.

CHAINS

The NW. tree is burned out, but all are identified and are in the position described in the field notes.

At exact corner point

Set an iron post 3 ft. long, 2 ins. diam., 26 ins. in the ground for cor. of secs. 26 and 35; with brass cap marked

T30S	
S26	
-----	S25
S35	
R1W	
1923.	

from which

A fir, 10 ins. diam., bears S.45*W., 23 lks. dist., marked T 30 S R 1 W S 35 B T: new B T.

A fir, 12 ins. diam., bears N.8*W., 40 lks. dist., marked T 30 S R.1 W.S 26 B T: new B.T.

Land, mountainous.

Soil, stony, clay loam; second and third rate.

Timber, fir, cedar, pine, and oak.

Undergrowth, fir, hazel, oak, lilac.

Retracement

Thence

S.89*39*W., retracing bet. secs. 26 and 35.

Over mountainous land, through heavy timber and dense undergrowth.

Desc. 530 ft. over NW. slope.

40.14 Fall 44 lks. S. of the $\frac{1}{4}$ sec. cor., which is a badly decayed fir post with marks still visible. The old bearing tree in sec. 35 is dead and fallen. In place of the decayed post

Set a basalt stone, 20x14x14 ins., 12 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face, from which