

County Surveyor's Record, Douglas County, Oregon

Retracement and Dependent Resurvey of Portion
of Subdivisional Lines in T. 30 S., R. 1 W.

CHAINS

Retracement

$$\frac{1}{4}$$

S14	S13
1923	

from which

A black oak, 7 ins. diam., bears S.6*E., 261 lks.

dist., marked $\frac{1}{4}$ S 13 B T: new B T.A pine, 13 ins. diam., bears N.44 $\frac{3}{4}$ *W., 253 lks.dist., marked $\frac{1}{4}$ S 14 B T: new B T.

Ascend 220 ft.

45.30 Trail, bears E. and W.

65.00 Desc. 25 ft. along E. slope.

75.04 Creek, 1 lk. wide, C. SE.

78.15 Creek, 1 lk. wide, C. SE.

80.84 Fall 24 lks. E. of the cor. of secs. 11, 12, 13 and 14,
located by reference to the original bearing trees, all
deadened by fire, the NE. tree completely burned out,
positions agree with the field notes.

At exact corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the
ground, for cor. of secs. 11, 12, 13 and 14, with brass
cap marked

T30S R1W	
S11	S12

S14	S13
1923	

No live trees within limits, raise mound of stone, 2 ft.
base, 1 $\frac{1}{2}$ ft. high, W. of cor.

The bearing and length of the S. half mile is N.0*08'E.,
40.33 chs., and of the N. half mile is N.0*29'W.,
40.51 chs.

Land, mountainous.

Soil, clay loam, stony in places, second and third rate.

Timber, fir, pine, cedar, and madrona.

Undergrowth, lilac, hazel, willow, laurel.