

Subdivision of T. 30 S., R. 1 W.

CHAINS

- 42.55 Leave river at bend, flows SW.
- 43.04 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground for witness cor. to the $\frac{1}{4}$ sec. cor., with brass cap marked

S13
 $\frac{1}{4}$ WC

S24
1923

from which,

A cedar, 12 ins. diam., bears N.51*E., 117 lks.
dist., mkd. W C $\frac{1}{4}$ S 13 B T

An alder, 10 ins. diam., bears S.18*W., 63 lks.
dist., mkd. W C $\frac{1}{4}$ S 24 B T

Asc. 300 ft. over NE. slope to sec. cor.

- 56.25 Creek, 7 lks. wide, C. SE.
- 70.12 Creek, 1 lk. wide, C. SW.
- 80.40 The cor. of secs. 13, 14, 23, and 24.

Land; mountainous.
Soil; stony, third rate.
Timber; fir and cedar.
Undergrowth; hazel, lilac, vine maple.

Retracement and Boundaries of H E S No. 195
Same Deputy and Contract

Note: Retracement Lines 1-2 and 4-1 are given in the notes of the retracement of the north and west boundaries of sec. 23.

From Cor. No. 2, hereinbefore described.
South, retracing, line 2-3.

- 1.10 Trail, bears E. and W.
Desc. 480 ft. over rocky SW. slope.

- 20.02 Fall 5 lks. E. of cor. No. 3, which is a granite stone firmly set, 10x10x5 ins. above ground, marked 3 H E S 195 on NW. face; from which
A yew, 6 ins. diam., bears S.73 $\frac{1}{2}$ *W., 23 lks.
dist., marked X 3 H E S 195 B T.