

County Surveyor's Record, Douglas County, Oregon

6755

Subdivisions of fractional T.30 S., R.2 W.
Same Deputy and Contract.

CHAINS	Va. 17*30'E.	
	North between secs. 35 & 36.	
30.00	Leave openings and enter thick timber, C. NE. & SW.	+50
40.00	Set $\frac{1}{2}$ sec. post and built stone mound, from which, A Fir, 24 in. diam., bears N.14*W., 18 lks. A Fir, 24 in. diam., bears N.26*E., 17 lks.	-50
42.76	A Fir, 36 in. diam.,	-5
80.00	Set post cor. secs. 25,26, 35 & 36, from which A Fir, 18 in. diam., bears S.88*W., 15 lks. A Fir, 15 in. diam., bears N.75*W., 18 lks. A Fir, 30 in. diam., bears N.60*E., 13 lks. A Fir, 18 in. diam., bears S.30*E., 66 lks.	-200
	Soil, second rate.	
	Land, hilly. about one third	
	Timber, /second rate Oak openings; balance thickly timbered with Fir, Cedar & Laurel.	
	Va. 18*30'E.	
	East on random between secs. 25 & 36.	
40.00	Let temporary $\frac{1}{2}$ sec. post.	
79.80	Intersect East boundary 25 lks N. of Cor. N.89*49'W., on true line between secs. 25 & 36	
39.90	Set $\frac{1}{2}$ sec. post, from which, A Laurel, 6 in. diam., bears N.40*E., 6 lks. A Fir, 6 in. diam., bears S.30*E., 12 lks.	-200
43.00	Branch, 2 lks wide, C. N.	
63.90	Branch, 5 lks wide, C. N.	+180
79.80	To sec. cor.	
	Soil, third rate.	
	Land, hilly.	
	Timber, Fir & Cedar.	
	Aug. 29th, 1857.	