

County Surveyor's Record, Douglas County, Oregon

6763

Subdivisions of fractional T. 30 S., R. 2 W.

CHAINS

Va. 19°30'E.

East, on random between secs. 11 & ~~16~~
14

40.00	Set temporary $\frac{1}{4}$ sec. post	
79.20	Intersect N.&S., line 14 lks S. of cor. S89°54'W, on true line between secs 11 & 14.	
39.50	Set $\frac{1}{2}$ sec. post, from which.	+200
	A Fir, 40 in. diam., bears N.5°E., 13 lks.	
	A Fir, 12 in. diam., bears S.85°W., 51 lks.	
45.00	Leave thick timber and enter openings, C. NW. & SE.	+50
79.20	To sec. cor.	+300
	Soil, third rate.	
	Land, hilly & high.	
	Timber, about half Fir & Pine openings balance Fir.	

Va. 20°5'E.

North, between secs. 33 & 34.

38.75	Descend rocky precipice nearly perpendicular about 100 feet	-200
40.00	Set $\frac{1}{2}$ sec. post and built stone mound from which, An Alder, 18 in. diam., bears N.76°W., 83 lks. A Fir, 12 in. diam., bears S70°E., 107 lks.	-150
40.25	Elk Creek, 25 lks wide, C. NW	level
60.85	Trail, C. E. & W.	+400
80.00	Set post cor secs. 27, 28, 33 & 34, from which An Oak, 6 in. diam., bears N.10°E., 25 lks. A Fir, 12 in. diam., bears S.20°E., 28 lks. A Laurel, 10 in. diam., bears N.54°W., 21 lks. A Dogwood, 6 in. diam., bears S.57°W., 23 lks.	-300
	Soil, third rate.	
	Land, very hilly.	
	Timber, sparsley timbered with Fir, Pine, Cedar, Oak and Laurel.	