

County Surveyor's Record, Douglas County, Oregon

Exterior Boundaries of T. 30 S., R. 3 W.  
As surveyed by William M. Bushey, Deputy Surveyor.  
Under Contract No. 620, dated June 17, 1893.

CHAINS

I am unable to find the  $\frac{1}{4}$  sec. cor. or either of the witness trees on the East bdy., of sec. 25, T. 30 S., R. 3 W. I find the 4 witness trees to the cor. to secs. 19, 24, 25 and 30, but the corner has been destroyed. At cor. point I set an Oak post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for cor. to secs. 19, 24, 25 and 30, marked T 30 S, <sup>S.</sup> 19 on NE, R 2 W, S 30 on SE, R 3 W, S 25 on SW and S 24 on NW, faces with 4 notches on N. and 2 notches on S. edges, from which,

An Oak, 12 ins. diam., (15 ins. now) bears N.45\*E, 59 lks. dist. marked T 30 S, R 2 W, S 19 B T.

An Oak, 12 in. diam. ( 15 ins. now) bears S.74\*E, 56 lks. dist., marked T 30 S, R 2 W, S 30 B T.

An Oak, 15 ins. diam., bears S.54\*W, 37 lks dist., marked T 30 S, R 3 W, S 25 B T.

An Oak, 12 ins. diam., (18 ins. now) bears N.38\*W., 141 lks. dist., marked T 30 S, R 3 W, S 24 B T, thence I run-

South on blank line bet secs. 25 and 30.

Var. 19 $\frac{1}{2}$ \*E at 7 A.M.

Descend in Oak timber and dense Oak brush

-400

31.60 Road course E and W.

34.30 To South Umpqua River course West

37.25 To South bank and ascend

+30

39.00 Ascend steeply

40.00 After diligent search I am unable to find the  $\frac{1}{4}$  sec. cor. or either of the witness trees. I therefore set a Quartz Stone 14x12x8 ins. 10 ins. in the ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  on W. face, from which,

An Alder, 10 ins. diam., bears N.34\*E., 7 lks. distant marked  $\frac{1}{4}$  S, B T.