

County Surveyor's Record, Douglas County, Oregon

Exterior Boundaries of T. 30 S., R. 3 W.

CHAINS

on W faces, with 1 notch on E and 5 notches on W faces from which,

A Cedar, 10 ins. diam., bears N.57 $\frac{1}{2}$ *E., 17 $\frac{1}{4}$ lks. dist. marked T 30 S, R 3 W, S 36 B T.

A Cedar, 10 ins. diam., bears N.51*W., 12 $\frac{3}{4}$ lks. dist. marked T 30 S, R 3 W, S 35 B T.

A Cedar, 12 ins. diam., bears S.42*E., 4 $\frac{1}{2}$ lks. dist. marked T 30 S, R 3 W, S 35 & 36 C C B T.

Soil, third rate.

Land, mountainous, 80.00 chs.

Heavily timbered with Fir, Laurel, Cedar and Maple, 80.00 chs.

Dense undergrowth of Vine-Maple, Hazel, Arrowwood, Laurel, Cedar and Fir, 75.00 chs.

Va. 18 $\frac{3}{4}$ *E.

West on a true line between secs. 2 and 35

Descend

-300

15.30 A stream 1 lk. wide, course NW. ascend

+75

19.00 Top of ridge and descend

-75

23.65 A stream 2 lks. wide course N.30*E., ascend

+400

40.00 A hemlock, 5 ins. diam., which I mark $\frac{1}{2}$ S on N face, for $\frac{1}{2}$ sec. cor. from which,

A Fir, 22 ins. diam., bears S.62 $\frac{1}{2}$ *W., 23 lks. dist. marked $\frac{1}{2}$ S B T.

A Fir, 30 ins. diam., bears N.79 $\frac{1}{4}$ *W., 38 lks. dist. marked $\frac{1}{2}$ S B T.

45.75 Top of ridge course N and S descend

-300

58.10 A spring branch, 1 lk. wide course NW.

59.08 A ravine, course NW and SE.

60.00 A ravine, course NW and SE.

62.40 A stream, 1 lk wide, course North ascend

+50