

County Surveyor's Record, Douglas County, Oregon

Exterior Boundaries of T. 30 S., R 3 W.

CHAINS		
	West on true line between Secs. 5 & 32 Va, 19 $\frac{1}{2}$ *E.	
	. Descend	-75
2.75	A ravine, course NW, and SE, ascend	+50
7.00	Descend	-40
10.00	Ascend	+50
15.75	Top of ridge, course NW and SE, descend	-500
40.00	Set a stone 12x12x8 ins. 8 ins. in the ground for $\frac{1}{2}$ sec. cor. marked $\frac{1}{2}$ on N. face, from which, A Fir, 30 ins. diam. bears N.71 $\frac{1}{2}$ *E., 15 $\frac{1}{2}$ lks. dist. marked $\frac{1}{2}$ S B T. A Live Oak, 10 ins. diam., bears S.15*W., ^{47$\frac{1}{2}$ lks.} dist. marked $\frac{1}{2}$ S B T.	
52.95	A stream 3 lks. wide course North ascend	+75
57.00	Descend	-200
62.57	A stream 15 lks. wide, course North Ascend	+500
80.00	Set a Fir post 4 ft. long, 4 ins. square 24 ins. in the ground for closing cor. to secs. 31 and 32, marked C C, T 30 S, R 3 W on N, S 32 on E, and S 31 on W faces with 5 notches on E and 1 notch on W faces, from which, A Fir, 7 ins. diam., bears N.28 $\frac{1}{2}$ *E., 33 $\frac{1}{2}$ lks. dist. marked T 30 S, R 3 W, S 32 B T A Fir, 9 ins. diam., bears N.23 $\frac{1}{2}$ *W, 48 lks. dist. marked T 30 S, R 3 W, S 31 B T	