

Exterior Boundaries T. 30 S., R. 3 W.

CHAINS		
	Soil, third rate.	
	Land, mountainous, 80.00 chs.	
	Heavily timbered with Fir, Laurel, Cedar and Maple 80.00 chs.	
	Dense undergrowth of Vine-Maple, Laurel, Hazel, Chincapin, Cedar and Fir, 74.00 chs.	
<hr/>		
	North bet. secs. 7 and 12.	
	Va. 19*E., at 3:30 P.M.	
	Ascend	+50
5.50	Top of ridge, course E and W, descend	-40
7.75	A stream, 2 lks. wide, course NE. ascend	+200
	Oct 6, 1893.	
12.55	A Fir, 40 ins. diam., on line marked with 2 notches on N and S sides.	
16.50	A stream, 3 lks. wide, course SE ascend	
39.50	Descend	-50
40.00	Set a Cedar post 4 ft. long 4 ins. square, 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W face, from which, A Fir, 36 ins. diam., bears S.61*W., 147 lks. dist. marked $\frac{1}{4}$ S B T. A Fir, 11 ins. diam., bears N.8 $\frac{1}{2}$ *E., 76 lks. dist. marked $\frac{1}{4}$ S B T.	
42.25	A stream, 2 lks. wide, course East ascend	+25
43.50	descend	-60
45.85	A stream, 2 lks. wide, course east, ascend	+40
50.50	Descend	-175
54.75	A Fir, 30 ins. diam. on line marked with 2 notches on N and S sides.	
66.50	A stream, 6 lks. wide, course East, ascend	+250