

## County Surveyor's Record, Douglas County, Oregon

Re-Survey of West Bdy., of T. 30 S., R 2 W.

## CHAINS

- 79.50 Ridge bears E and W.
- 80.02 The closing cor. of secs. 18 and 19.  
Land, mountainous.  
Soil, clay and granite, second and third rate.  
Timber, Fir, Hemlock, Cedar, undergrowth, Vine-Maple  
Hemlock, Hazel.  
Mountainous or heavily timbered land or land covered  
with dense undergrowth and exceptionally difficult  
to survey, 80.02 chs.
- 
- South on W. bdy. sec. 19  
Over mountainous land, heavily timbered and covered  
with dense undergrowth.  
Desc. S. slope.
- 2.12 The cor. of secs. 13 and 24, T 30 S, R 3 W.
- 3.30 Creek, 2 lks. wide, course W.
- 12.60 Wagon road, Coffee Creek to Pardue, bears NE and SW.
- 19.30 Creek, 1 lk. wide, course SW.
- 38.75 Creek, 2 lks. wide. course SW.
- 40.00 A Maple, 4 ins. diam., for  $\frac{1}{4}$  sec. cor. on W bdy. sec.  
19. I mark  $\frac{1}{4}$  S 19 on E side, from which,  
A Maple 12 in. diam. bears N.86\*E., 48 lks. dist.  
marked  $\frac{1}{4}$  S 19 B T.  
A Maple 8 in. diam., bears S.34 $\frac{1}{2}$ \*E., 16 lks. dist.  
marked  $\frac{1}{4}$  S 19 B T.
- 42.65 I re-establish the old  $\frac{1}{4}$  sec. cor. in its original  
position as the  $\frac{1}{4}$  sec. cor. on E. bdy. sec. 24,  
T 30 S, R 3 W, only, as follows:  
No stones available, set a Cedar post, 3 ft. long,  
4 ins. sq., 24 ins. in the ground for  $\frac{1}{4}$  sec. cor.  
on E. bdy. sec. 24, marked  $\frac{1}{4}$  S 24 on W face, from  
which,  
A Fir, 10 ins. diam., bears S.50\*W., 18 lks.  
dist. marked  $\frac{1}{4}$  S 24 B T.