

Re-survey of West Bdy., of T. 30 S., R 2 W.

CHAINS

A Fir, 28 ins. diam., bears N.88*W., 36 lks. dist.
marked $\frac{1}{4}$ S 24 B T.

50.00 Ridge bears NE. and SW.

83.00 The cor. of secs. 19, 24, 25 and 30.

Land, Mountainous.

Soil, clay and granite, second and third rate.

Timber, Fir, Hemlock, Oak.

Undergrowth, Oak, Hazel, Fir.

Mountainous or heavily timbered land or land covered
with dense undergrowth and exceptionally difficult
to survey, 83.00 chs.

September, 1, 1909.

Retracement of East Bdy., of T.30 S., R. 3 W.
Same Deputy and Contract.

September 6: At 8 A.M. 1.m.t. I set off 42*55' in the
lat. arc. 6*33'N., on the decl. arc. and determine
a meridian with the solar at the cor. of secs. 25 and
36 on E. bdy. of T. 30 S, R 3 W. Thence I retrace
South on E. bdy. sec. 36 T 30 S, R 3 W.

40.19 The $\frac{1}{4}$ sec. cor. which is decayed post, witnessed as
described by the surveyor general, bears E 81 lks.
dist., the course of this line is S.1° 9'E., and the
distance is 40.19 chs.

Commencing at the $\frac{1}{4}$ sec. cor. I retrace South on E.
bdy. sec. 36, T 30 S, R 3 W.

31.54 The cor. of Tp 30 S, R's 2 and 3 W, which is a Fir post
4 in. sq., 12 ins. above ground, marked and witnessed
as described by the surveyor general, bears E 36 lks.
dist.

The course of this S.0*39'E., and the distance is
31.54 chs.