

## Re-survey of Subdivision Lines of T. 30 S., R. 2 W.

CHAINS

23.90

A spring flows N.

Ascend NE. slope.

28.50

Bench on N. slope.

29.75

Leave bench.

Along bluff of river.

35.25

Leave river bluff and ascend NE. slope.

40.00

Set a granite stone 15x8x6 in., 10 ins. in the ground, for  $\frac{1}{4}$  sec. cor. on N bdy. sec. 31, marked  $\frac{1}{4}$  on S face, from which,

A Fir, 20 ins. diam., bears S.55\*E., 56 lks. dist. marked  $\frac{1}{4}$  S 31 B T.

A Maple, 8 ins. diam., bears S.39\*W., 15 lks. dist. marked  $\frac{1}{4}$  S 31 B T.

40.88

Reported position of old  $\frac{1}{4}$  sec. cor. no trace of this cor. can be found after diligent search.

Set a granite stone 18x12x10 ins. 12 ins. in the ground for  $\frac{1}{4}$  sec. cor. on S bdy. sec. 30, marked  $\frac{1}{4}$  on N face, from which,

A Dogwood, 9 ins. diam., bears N.21\*E., 35 lks. dist. marked  $\frac{1}{4}$  S 30 B T.

An Alder, 6 ins. diam., bears N.70 $\frac{1}{2}$ \*W., 24 lks. dist. marked  $\frac{1}{4}$  S 30 B T.

Land, mountainous.

Soil, stony third and fourth rate.

Timber, Fir, Hemlock, Maple.

Undergrowth, Vine-Maple, Fir, Oak.

Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey, 40.88 chs.

September 5, 1909