

## Re-survey of Subdivision Lines of T. 30 S., R 2 W.

## CHAINS

September 9: at this cor. I set off 5\*21'N., on the decl.  
arc. and at 11 h. 57 m. a. m. l. m. t. observe the sun  
on the meridian. The resulting lat. is 42\*54'

Thence I run

North on a true line between secs. 32 and 33.

Over mountainous land, heavily timbered and covered  
with dense undergrowth.

Descend N. slope.

6.50 Creek, 2 lks. wide, course NE.

Descend gradually along E' slope.

37.75 Creek, 1 lk. wide, course E.

40.38 Set a granite stone 15x12x10 ins. 10 ins. in the ground  
for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  on W. face, from which,  
A Fir, 8 ins. diam. bears S.67 $\frac{1}{2}$ \*E., 12 lks. dist.  
marked  $\frac{1}{4}$  S 33 B T.

A Madrone, 15 ins. diam., bears N.76\*W., 19 lks.  
dist. marked  $\frac{1}{4}$  S 32 B T.

45.50 Ridge point descending NE.

Descend steep N. slope.

61.00 Enter river bottom.

68.00 S. umpqua river, 100 lks. wide, course W.

71.50 Wagon road bears E. and W.

72.50 Leave river bottom and ascend steep S' slope.

80.76 The cor. of secs. 28, 29, 32 and 33

Land, mountainous

Soil, Loam and stony, second and third rate.

Timber, Fir, Hemlock, Cedar.

Undergrowth, Hazel, Vine-Maple,

Mountainous or heavily timbered land or land covered  
with dense undergrowth and exceptionally difficult  
to survey, 80.76 chs.

September 9, 1909.