

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 30 S., R. 2 W.

CHAINS	
	Asc. N. slope.
58.00	Ridge bears E. and W.
	Desc. S. slope.
61.00	A cabin bears E., 150 lks. dist..
70.25	Creek, 2 lks. wide, course SW.
71.50	Creek, 5 lks. wide, course W.
	Asc. N. slope.
80.00	Summit of ridge bears E. and W.
	Set a slate stone 15x8x6 ins., 10 ins. in the ground,
	for cor. of secs. 17, 18, 19 and 20, marked with
	3 notches on S. and 5 notches on E. edge, from which,
	A Fir, 12 ins. diam., bears N.42 $\frac{1}{2}$ *E., 10 lks. dist.
	marked T 30 S R 2 W S 17 B T.
	A Fir, 12 ins. diam., bears S.22 $\frac{1}{2}$ *E., 12 lks. dist.
	marked T 30 S R 2 W S 20 B T.
	A Madrone, 15 ins. diam., bears S.34*W., 35 lks.
	dist. marked T 30 S R 2 W S 19 B T.
	A Fir, 10 ins. diam., bears N.41 $\frac{1}{2}$ *W., 50 lks. dist.
	marked T 30 S R 2 W S 18 B T.
	Land, mountainous.
	Soil, granite and clay, 2nd and 3rd rate.
	Timber, Fir, Hemlock, Cedar.
	Undergrowth, Vine Maple, Hemlock, Hazel.
	Mountainous or heavily timbered land or land covered
	with dense undergrowth and exceptionally difficult
	to survey, 80.00 chs.
	<hr/>
	East on a random line bet. secs. 17 and 20.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
79.78	Intersect N. and S. line, 44 lks. N. of the cor. of secs.
	17 and 20 on W. bdy. sec. 16.
	Thence I run
	N.89*41'W. on true line bet. secs. 17 and 20.