

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 30 S., R. 2 W.

CHAINS

witnessed as described by the surveyor general.

Set a granite stone 15x12x5 ins., 10 ins. in the ground for closing cor. of secs. 30 and 31, marked C C on E. with 5 grooves on N. and 1 groove on S. face, from which,

A Maple, 15 ins. diam., bears N.56 $\frac{1}{2}$ *E., 27 lks. dist. marked T 30 S R 2 W S 30 B T.

A Maple, 10 ins. diam., bears S.58*E., 37 lks. dist. marked T 30 S R 2 W S 31 B T.

Obliterate marks on former bearing trees at the old cor. referring to secs. 30 and 31.

From the closing cor. of secs. 30 and 31, I run East on a true line bet. secs. 30 and 31.

Over mountainous land, heavily timbered and covered with dense undergrowth.

Desc. E. slope.

2.80 Creek, 6 lks. wide, course N.

Asc. steep W. slope.

16.00 Ridge bears N. and S.

Desc. E. slope.

23.75 Begin steep descent.

35.00 Creek, 1 lk wide, course NE.

37.00 Ridge point descending NE.

Desc. NE. slope.

41.15 The $\frac{1}{4}$ sec. cor. on S. bdy. sec. 30.

The $\frac{1}{4}$ sec. cor. on N. bdy. sec. 31 bears E. 88 lks. dist.

Land, mountainous.

Soil, granite and stony, 2nd and 4th rate.

Timber, Fir, Hemlock, Cedar.

Undergrowth, Lilac, Hazel, Vine Maple.

Mountainous or heavily timbered land or land covered with dense undergrowth and exceptionally difficult to survey, 41.15 chs.

September 5, 1909.