

Subdivisions of Fractional T. 30 S., R. 3 W.

CHAINS

General Description.

There is a narrow strip of country along the South Umpqua which runs through the township and a very little in the NW. part adapted to settlement. The balance of the township is very mountainous and unfit for settlement.

Resurvey of Exterior Lines of T. 30 S., R. 4 W., as surveyed by Wm Thiel, Deputy Surveyor, under Contract No 535, dated February 5, 1889.

I begin at the cor. to Tps. 30 and 31 S., Rs. 3 and 4 W. the post of which is gone, but the following bearing trees are standing.

A Laurel, 10 ins. diam., marked T 30 S R 3 W S 31 B T.

A Laurel, 9 ins. diam., marked T 30 S R 4 W S 36 B T.

A Laurel, 9 ins. diam., marked T 30 S R 4 W S 1 B T.

A Laurel stump, in sec. 6 corresponding in size and direction with description in field notes. I restore this cor. by setting a Laurel post, 4½ ft. long 4 ins. sq., 24 ins. in the ground marked, T 30 S S 31 on NE R 3 W S 6 on SE T 31 S S 1 on SW R 4 W S 36 on NW faces, with 6 notches on each edge, from which

A Laurel, 10 ins. diam., bears N.60°E., 34 lks. dist., marked T 30 S R 3 W S 31 B T.

A Laurel, 9 ins. diam., bears S.31°W., 40 lks. dist., marked T 31 S R 4 W S 1 B T.

A Fir, 12 ins. diam., bears S.51°E., 45 lks. dist., marked T 31 S R 3 W S 6 B T.

A Laurel, 9 ins. diam., bears N.16°W., 50 lks. dist., marked T 30 S R 4 W S 36 B T.

The Laurels, are the original bearing trees, which I remember.