

Resurvey of Exterior Lines of T. 30 S., R. 4 W.

CHAINS

I run thence

North, on a random line between secs. 36 and 31, Va. 19*
35'E., through Fir, timber with heavy underbrush.

38.10 $\frac{1}{4}$ sec. cor. bears E. 275 lks.

75.15 Intersect N. boundary of sec. 36, 314 lks. W. of cor.
to secs. 36, 25, 30 and 31, the post, set for this
cor. is gone, but all of the Fir bearing trees are
standing and easily identified by their marks namely.

A Fir, 48 ins. diam., marked T 30 S R 3 W S 31 B T.

A Fir, 30 ins. diam., marked T 30 S R 3 W S 30 B T.

A Fir, 30 ins. diam., marked T 30 S R 4 W S 25 B T.

A clump of small Laurels are growing in sec. 36,
corresponding in direction and distance described in
the field notes furnished me. I restore this cor.
by setting a Laurel post, 4 $\frac{1}{2}$ ft. long, 4 ins. diam.,
24 ins. in the ground, marked T 30 S S 30 on the NE
R 3 W S 31 on the SE R 4 W S 36 on the SW S 25 on
NW faces, with 5 notches on N and 1 notch on S edges,
from which

A Fir, 30 ins. diam., bears N.30'E., 13 lks. dist.,
marked T 30 S R 3 W S 30 B T.

A Fir, 48 ins. diam., bears S.45'E., 30 lks. dist.,
marked T 30 S R 3 W S 31 B T.

A Fir, 20 ins. diam., bears S.41'W., 55 lks. dist.,
marked T 30 S R 4 W S 36 B T.

A Fir, 30 ins. diam., bears N.30'W., 13 lks. dist.,
marked T 30 S R 4 W S 25 B T.

The bearing trees in secs. 30, 31 and 25 are the old
bearing trees which I freshly marked, old marks being
dim.

Thence

S.0*36'W., on true line between secs. 36 and 31, Va.19*
30'E.