

Resurvey of Exterior Lines of T. 30 S., R. 4 W.

CHAINS		
	Ascending N. slope of mountain in big Fir timber with heavy undergrowth alongside and West of Canyon course.	
8.25	Pass from West side to East side of canyon 50 ft. deep.	
29.00	Leave N. slope and pass on E. slope of ridge. Va. 19*35'E	
37.05	$\frac{1}{2}$ sec. cor. post is gone, both bearing trees are standing. I restore this cor. by setting a Laurel post, 3 ft. long, 3 ins. sq., 24 ins. in the ground marked $\frac{1}{2}$ S. on the W. face, from which A Fir, 40 ins. diam., bears S.60*W., 10 lks. dist., marked $\frac{1}{2}$ S B T. A Fir, 33 ins. diam., bears S.48*E., 36 lks. dist., marked $\frac{1}{2}$ S B.T. I remark both trees, the marks being dim and overgrown. Thence S.4*9'W., on true line between secs. 36 and 31. Ascending through Fir timber.	
1.50	A Gulch, course East.	
13.00	A canyon, course NE. 40 ft. deep.	
27.00	Top of East end of ridge, course East and West, begin descent.	+500
38.10	The cor. to secs. 31, 6, 1 and 36, Tps. 30 and 31 S., Rs. 3 and 4 W. Land mountainous. Soil, coarse gravel, 3rd rate. Timber, mostly Fir, Laurel, Chinquapin and Cedar. Undergrowth, Huckleberry, Hazel, small Firs and Laurel.	
	April 25.	