County Surveyor's Record, Douglas County, Oregon

Resurvey of Exterior of T. 30 W., R. 4 W.

CHAINS	
	standing. I restore this cor. by setting a quartz rock, 12 x 10 x 6, 8 ins. in the ground, marked ½ on W. face, from which
	A B. Oak, 24 ins. diam., bears N.78*W., 145 lks. dist., marked ¼ S B T.
	A B. Oak, 30 ins. diam., bears S.85*E., 24 lks. dist., marked ¼ S B T.
	I remark these trees the old marks being dim, and overgrown.
	Thence
	S.1*7'E., on true line between secs. 25 and 30.
	Va. 19*22'E
1.25	Foot of hill and countyroad to Canyonville, course East and West.
1.50	Enter grainfield, bears East and West.
4.00	Enter low level bottom, bears East and West.
17.25	Leave field, enter timber and brush.
34.50	Right bank of S. Umpqua, set flagg on S. bank, run base West 1.00 chs. Flagg bears S.22*40'E., making 2.39 cross.
36.89	Left bank of river, ascend in bluff.
37.79	The cor. to secs. 25, 36, 30 and 31.
	Land, S. half level, N. half rolling.
	Soil, S. half loam, 1st rate. N. half gravelly, 3rd rate.
	Timber, Oak, Fir, Laurel, Maple.
	Undergrowth, mostly young Oaks, Laurels and Hazel.
	Latitude observed, 42*56'N.
	North, on a random line between 24 and 19.
	Va. 19*20'E
39.30	¼ sec. cor., bears W. 59 lks. dist.