

Resurvey of Exterior Lines of T. 30 S., R. 4 W.

CHAINS

A Maple, 10 ins. diam., bears S.19°E., 38 lks. dist., marked T 30 S R 3 W S 7 B T.

A W. Fir, 15 ins. diam., bears S.18°W., 32 lks. dist., marked T 30 S R 4 W S 12 B T. (This is the old bearing tree which I remark.)

A Red Fir, 9 ins. diam., bears N.39½°W., 31 lks. dist., marked T 30 S R 4 W S 1 B T.

Thence

S.1°55'W., on true line between secs. 12 and 7.

Va. 19°10'E

- 2.25 Days Creek, course W. 40 lks. wide.
- 9.50 Leave timbered bottom, begin ascent.
- 19.00 A more gradual ascent of E. slope of spur, course E. and W. heavy underbrush.

34.05 ¼ sec. cor. A post, without marks is standing. I replace it by a Fir post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, marked ¼ S. on W. face, from which

+400

A B. Oak, 12 ins. diam., bears N.48°E., 12 lks. dist., marked ¼ S B T. (This has been chopped into, and the old marks destroyed. I remark same.)

A Red Fir, 12 ins. diam., bears S.49½°W., 38 lks. dist., marked ¼ S B T.

The B. Oak, in sec. 12 has fallen down, but corresponds in size and direction with the one described in the field notes furnished.

Thence

S.1°43'W., on true line between secs. 12 and 7.

Va. 19°10'E

- Ascend an open timber flat, bears E. and W.
- 7.00 Along NE. slope of mountain, thick underbrush.
- 17.50 Pass from the NE. slope to E. slope.